

Oil Field Environmental Incident Summary

Incident: 20150106143240 **Date/Time of Notice:** 01/06/2015 14:32

Responsible Party: Brenntag Pacific, Inc.

Well Operator:

Well Name: Lost Bridge Compressor Station

Field Name:

Well File #:

Date Incident: 1/2/2015 **Time Incident:** 13:00

Facility ID Number:

County: DUNN

Twp: 147

Rng: 96

Sec: 25

Qtr:

Location Description:

Submitted By: Jason Lyons

Received By:

Contact Person: Mark Jensen
2752 E. Villard St.
Dickinson, ND 58601

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	25	Gallons	15	Gallons		

Description of Other Released Contaminant:

Methanol

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

There were no off-site impacts or immediate risks to human health or the environment.

Areal Extent:

10 feet by 30 feet

Potential Environmental Impacts:

There were no impacts to surface water or groundwater.

Action Taken or Planned:

The operator was able to recover the majority of the released material with absorbent. Clean Harbors was contacted to recover the remaining material.

Wastes Disposal Location: Recovered wastes will be collected by Clean Harbors and disposed in accordance with applicable State/Federal regulations.

Agencies Involved:**Updates**

Date: 1/6/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill occurred at a location not associated with E & P. Followup is necessary.

Date: 2/5/2015 **Status:** Inspection

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on site with minimal environmental risk. Impacts have been remediated. No further action is warranted.